

34607-1A

Digital Torque Adapter

- Accuracy : ±2%
- Memory : 50
- Display Resolution : 0.1 N·m / ft·lb ,0.01 kgf·m
- Operation Mode : Peak/Trace
- Unit Selection : kgf·m, ft·lb, N·m
- Battery : AA x 2 PC.(Battery not included)
- Battery Life : 110hrs (continuous operation)
- Operating Ambient Temperature : -10ºC - 60ºC (13.9ºF -139.9ºF)
- Storage Temperature : -20ºC - 70ºC (-4ºF - 157.9ºF)
- Operating Relative Humidity : 15 to 90% noncondensing
- Switch off Automatically: 70 seconds (if do not use electronic torque adapter.)
- LED indicator : Green. Red
- Overload Alarm : 1,250 N·m (922 ft.lb.)
- Calibration must be done regularly to ensure accuracy. Suggested calibration period is at least every 12 months or 5000 times of usage











Item	Square Drive	Torque Range Nm	Torque Range ft · lb	Torque Range kgf. cm	Size mm	g	
34607-1A-1	3/4"	200~1000 N·m	147.6~738 ft·lb	20.4~102 kgf·m	L110 x W56 x H60	585	6 / 24