



34407-1A



Digital Torque Adapter

- Accuracy : $\pm 2\%$
- Memory : 50
- Display resolution : 0.1 N·m / ft·lb , 0.01 kgf.m
- Operation Mode : Peak/Trace
- Unit Selection : kgf·m, ft·lb, N·m
- Battery : AAA x 2 PC.(Battery not included)
- Battery Life : 110hrs (continuous operation)
- Operating Ambient Temperature :
-10°C - 60°C (13.9°F -139.9°F)
- Storage Temperature :
-20°C - 70°C (-4°F - 157.9°F)
- Operating relative humidity :
15 to 90% noncondensing
- Auto shut off : 70 seconds (if do not use electronic torque adapter.)
- LED indicator : Green. Red
- Overload Alarm :
34207-1A: 37.5 N·m (27.6 ft.lb.)
34307-1A: 168.8 Nm(124.5 ft.lb.)
34407-1A: 250 N·m (184.4 ft.lb.)
- Calibration must be done regularly to ensure accuracy. Suggested calibration period is at least every 12 months or 5000 times of usage



Item	Square Drive	Torque Range Nm	Torque Range ft · lb	Torque Range kgf·m	Size mm		
34207-1A-1	1/4"	6~30 N·m	4.4~22.1 ft·lb	0.61~3.06 kgf·m	L75 x W45 x H40	124	12 / 48
34307-1A-1	3/8"	27~135 N·m	19.9~99.6 ft·lb	2.75~13.76 kgf·m	L75 x W45 x H40	198	12 / 48
34407-1A-1	1/2"	40~200 N·m	29.5~147.5 ft·lb	4.08~20.38 kgf·m	L75 x W45 x H40	198.5	12 / 48