



# 6BE11-07



## Soldering Aid (Brush / Scraper)

- Brush / Scraper
- For removing flux residue and surplus solder



| Item     | Size<br>mm |  |  |
|----------|------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 6BE11-07 | 175        | 15                                                                                  | 1 / 200                                                                               |