

6BE11-07

Soldering Aid (Brush / Scraper)

— Brush / Scraper

— For removing flux residue and surplus solder





Item	Size mm	g	
6BE11-07	175	15	1 / 200