

The diagram shows the control panel with the following labels and buttons:

- Labels: Pos, Bar, PSI, (psi), P, T, show
- Display: 8.8.8.8.8
- Buttons: ▲, P/T, ▼, M, and a red button with a white '0'.
- A red arrow points to the red button with a white '0'.

The diagram shows the device's LCD screen with the following data:

KPa	Bar	Psi	Kg/cm²	P	T	Chk
						0.0
						0.0
						0.0
						0.0
						0.0
						0.0

The main display shows **29.5** in red. Below the screen, the **M** button is highlighted with a red arrow, indicating it is the correct button to press for this function.

Regler le couple: Arreglar es par: Перинормка задаваемого усилия


Ustawić siłę: ضبط العزم Nyomaték beállítás: 調整扭力: 調整力

[illegible]

- ▶ LCD display shows real-time torque values as applying.
- ▶ Durante o uso o LCD mostra os valores de torque em tempo real.
- ▶ Anzeige der Drehmomente in Echtzeit auf dem LCD-Display.
- ▶ L'écran LCD affiche les valeurs de couple appliquées en temps réel.
- ▶ La pantalla LCD enseña los valores del par que se aplican en tiempo real.
- ▶ Измерен моментом вращения момент в режиме реального времени.
- ▶ Na wyświetlacz pokazujemy jest aktualny moment w czasie rzeczywistym.

القياسات لحظية الزوايا التواء العزم

- ▶ Haseztalt közben az LCD kijelző az aktuális nyomaték értéket mutatja.
- ▶ 液晶显示屏实时显示力矩。
- ▶ 螢幕會顯示即時扭力數值。



Ódcsolya pamljei: قراءة ذاكرة العزم
 A mómórírában tárolt nyomatlak értéklak kivolásza: 记忆读取 記憶读取

The diagram shows a pressure gauge with a digital display showing 'P06'. Below the display are four buttons: an up arrow, a 'P/T' button, a down arrow, and a red 'M' button. A red hand icon is pointing to the 'M' button. To the right of the buttons is a power symbol button. The gauge has a threaded port at the bottom and a side port on the right.

LCD display shows the maximum torque value which can be checked after use.
LCD mostra apenas o valor máximo de torque atingido, o qual pode ser checado após o uso.
Nach dem Anwenden wird das maximale Drehmoment auf dem Display angezeigt.
L'ecran LCD affiche la valeur maximale du couple seulement, ce qui peut être vérifié après utilisation.
La pantalla LCD enseña el valor de par máximo, que se puede comprobar después de su uso.
Дисплей показывает только максимальное приращение усилия.
Na wykrętkownicy pokazywana jest tylko siła. Można zostawić.

القيمة القصوى لعزم الدوران يمكن التحقق منها بعد الاستخدام
Az LCD kijelző csak a maximális forgatónyomatékot mutatja, amit a használat után lehet ellenőrizni.
L'ecran LCD n'indique que la valeur maximale du couple, ce qui peut être vérifié après utilisation.
Az LCD kijelző csak a maximális forgatónyomatékot mutatja, amit a használat után lehet ellenőrizni.
Дисплей показывает только максимальное приращение усилия.
На выкрутке не показывается максимальная сила, которую можно использовать.

Plato

Hand icon pointing to the 'Plato' button.

Válassza ki a nyomatékot/Abrons nyomás mód
調壓圧力/胎壓模式



1

[illegible]

Tire pressure check Verificação da pressão do pneu
Reifendruckkontrolle Verificar la presión del pneu
Comprobar la presión del neumático Проверка давления
sprawdzenie ciśnienia w oponie اطلاق دھنیں ریست

Abnorms nyomás ellenőrzés 胎压检查 胎壓檢查



4



KING TONY

NO.34407T-1A

2 IN 1 DIGITAL TORQUE AND TIRE PRESSURE GAUGE



















www.kingtony.com



Enjoy your work

(+)Increase

LED

LCD

Trace & Peak

Battery Cap

(-)Decrease

Buzzer

Power

Memory

034407T-1A.E_01 1PC.

4 712755 848344

KING TONY

Always wear eye protection while using this tool

Do not use the hammer to hit the tools

Model NO. 34407T-1A

Accuracy	±2%
Memory	50
Torque range	40-200 N-m (29.5~147.5 lb-ft)
Display resolution	0.1 Nm/ ft.lb / 0.01 kgf.m / 1.0 lb.in
Pressure range	1-100 psi(0.069~6.9 bar)
Display resolution	1Psi / 0.001 Bar /0.001 kgf-cm²/ 0.01 Kpa
Drive	1/2 inches
Operation Mode	Peak/ Trace
Unit selection	Kg-cm, kg-m, lb-in, lb-ft, N-m kpa, bar, psi, kg-cm²
Size	L75 x W67 x H46 mm
Weight	230g (battery included)
Battery	AAAx2 pcs
Battery Life	50 hrs (continuous operation)
Operating Ambient Temperature	-10°C ~ 60°C(13.9°F ~ 139.9°F)
Storage Temperature	-20°C ~ 70°C (-4°F ~ 157.9°F)
Operating relative humidity	15 to 90% noncondensing
Auto shut off	60 Seconds

✉ : service@kingtony.com
8934407TAEKT 166x85mm

Válassza ki a nyomatékot/Abrons nyomás mód
調壓圧力/胎壓模式



1

[illegible]

Tire pressure check Verificação da pressão do pneu
Reifendruckkontrolle Verificar la presión del pneu
Comprobar la presión del neumático Проверка давления
sprawdzenie ciśnienia w oponie اطلاق دھنیں ریست

Abnorms nyomás ellenőrzés 胎压检查 胎壓檢查



4

- ▶ 請不要在電源關閉時，使用電子扭力接頭。
- ▶ 請不要在電源關閉時，使用電子扭力接頭。

