

Torque Angle Adapter


34417-1A 1/2"

▪ Specifications:

Accuracy	Clockwise:±2% Anti-Clockwise:±2%				
Memory	10				
Unit Selection	N·m	ft·lb	In·lb	Kgf·m	Kgf·cm
Display Resolution	0.1	0.1	1	0.01	1
Operation Mode	Torque / Angle / Torque+Angle				
Battery	DC3V, CR2032				
Battery Life	4hrs (continuous operation)				
Operating Ambient Temperature	-10°C - 60°C (14°F - 140°F)				
Storage Temperature	-20°C - 70°C (-4°F - 158°F)				
Operating Relative Humidity	15 to 90% noncondensing				
Switch Off Automatically	100 seconds				
Warning Light	Green, Yellow, Red				
Overload Alarm	240 N·m (177 ft·lb)				



4
PC.



Calibration adapter




Torque Angle Adapter



- The LED screen is backlit for easier reading



- The ring-shaped warning light can provide an immediate visual cue for the torque values



- The body can be rotated 240° for easier reading



- This tool can also be used for torque testing for torque wrenches

Dual Scale - Newton Meter & English & Kilogram-force meter (N·m / ft·lb & kgf·m)

KT NO.	Square drive	Torque range			Tare	Box / Carton
		N·m	ft·lb	kgf·m		
34417-1A	1/2"	40 ~200 N·m	29.5~147.5 ft·lb	4.08~20.38 kgf·m	620	1 / 24